Rob Check out the Circled Language on this akowane.

Serial No. 10/623,670

67022-006

AMENDMENTS TO THE CLAIMS:

Please amend the claims as follows. This listing of claims will replace all prior listings.

1.-43. (Cancelled)

- 44. (Currently Amended) The concrete wall assembly of Claim 26-A concrete wall assembly comprising:
 - a frame comprising a plurality of study extending along a vertical direction;
- a first panel and a second panel fastened to said plurality of studs, said first panel and said second panel spanning said plurality of studs to define a concrete receiving cavity between said first panel and said second panel and said plurality of studs, wherein at least one of said first panel and said second panel comprises an insulative panel;


a port having a top and a bottom;

port; and a port concrete receiving cavity defining at least one of said top and said bottom of said

window opening, said window opening comprises a concrete indentation, wherein said port comprises a window opening, said window opening comprises a concrete indentation to receive a window frame.

- 45. (Previously Presented) The concrete wall assembly of Claim 44 wherein said removable block is located near the lower portion of said port in a vertical direction.
- 46. (Previously Presented) The concrete wall assembly of Claim 44 wherein said removable block is located on an exterior side of said wall assembly.
- 47. (Previously Presented) The concrete wall assembly of Claim 44 wherein said concrete indentation is located near the lower portion of said port in a vertical direction.

- 48. (Previously Presented) The concrete wall assembly of Claim 44 wherein said concrete indentation is located on an exterior side of said wall assembly.
- 49. (Cancelled)



- 51. (Currently Amended) The concrete wall assembly of Claim 49–50 wherein said removable block is located near the lower portion of said port in a vertical direction.
- 52. (Currently Amended) The concrete wall assembly of Claim 49–50 wherein said removable block is located on an exterior side of said wall assembly.
- 53. (Currently Amended) The concrete wall assembly of Claim 49 50 wherein said concrete indentation is located near the lower portion of said port in a vertical direction.
- 54. (Currently Amended) The concrete wall assembly of Claim 49–50 wherein said concrete indentation is located on an exterior side of said wall assembly.